



SMITH & WESSON



.38 CENTENNIAL MODEL No. 40

PARTS LIST • INSTRUCTIONS FOR USE • MAINTENANCE
SPECIFICATIONS • GUARANTEE



SPECIFICATIONS

Caliber38 S&W Special	Sights	Fixed, 1/10-inch serrated ramp front; square notch rear
Number of Shots	5	Frame	Round or square butt
Barrel	2"	Stocks	Smooth walnut Magna with S&W monograms
Length Over All	6½ inches	Finish	S&W Blue or Nickel
Weight	19 ounces	Ammunition38 S&W Special, .38 S&W Special Mid Range

SMITH & WESSON, INC.
SPRINGFIELD, MASS., U.S.A.

SMITH & WESSON

.38 CENTENNIAL

MODEL No. 40

PARTS LIST

PRICES EFFECTIVE JANUARY 1, 1960 — Subject to Change Without Notice — MINIMUM ORDER 50¢

No.	Name	Price	No.	Name	Price
5014	Extractor Pin	\$.10	5303	Trigger Lever Pin	\$.10
5045	Locking Bolt Spring20	5304	Hand Spring Pin10
5054	Bolt Plunger Spring25	5307	Locking Bolt Pin10
5054	Sear Spring25	5309	Mainspring Rod	1.60
5062	Stock Pin10	5311	Plate Screw, Crowned20
5074	Rebound Slide Spring50	5313	Rebound Slide	2.50
5091	Plate Screw, Flat Head20	5317	Sear90
5134	Barrel, 2"	12.00	5318	Yoke	5.60
5147	Locking Bolt80	5320	Side Plate	6.50
5203	Barrel Pin10	5325	Escutcheon30
5216	Mainspring Rod Swivel90	5326	Escutcheon Nut30
5220	Center Pin	1.00	5336	Trigger	3.75
5227	Center Pin Spring20	5337	Trigger Lever50
5231	Cylinder with Extractor and Pins	14.00	5355	Bolt Plunger20
5239	Extractor	4.00	5366	Safety Latch50
5255	Extractor Rod	1.00	5367	Safety Latch Pin10
5260	Extractor Spring30	5368	Safety Lever	2.50
5277	Hammer Stud60	5369	Safety Lever Pin10
5278	Cylinder Stop Stud50	5369	Safety Lever Disengaging Pin10
5278	Rebound Slide Stud50	5370	Safety Lever Spring20
5278	Trigger Stud50	5493	Stock, Magna, Left	2.50
5280	Hammer Nose Bushing50	5494	Stock, Magna, Right	2.50
5281	Frame Lug50	5610	Bolt	2.60
5289	Hammer	3.50	5659	Thumbpiece	2.00
5292	Hammer Nose75	5723	Stock Screw30
5293	Hammer Nose Rivet20	5742	Frame, with Studs, Bushing and Lug	30.00
5296	Hand with Stud	1.20	5749	Mainspring60
5301	Hand Pin10	5839	Thumbpiece Screw30
5302	Hand Torsion Spring20	5924	Cylinder Stop	1.50
5303	Hand Spring Torsion Pin10	5959	Cylinder Stop Spring20
5303	Sear Pin10			

SERVICE

Should your Smith & Wesson revolver require adjustment, repair or refinishing, we recommend most sincerely that the weapon be returned to the factory. There is no other way to insure that the work will be done in a properly equipped and staffed shop.

Charges are very reasonable, being based on the cost of parts replaced plus a labor charge for the time expended on the job. A labor charge for one hour is usually sufficient to cover all but very extensive overhaul jobs.

Revolvers returned to the factory should be **MARKED FOR THE ATTENTION OF THE SERVICE DEPARTMENT.** A letter of instructions should be enclosed with the gun, and shipment

by individuals must be made by Prepaid Railway Express. Adherence to these suggestions will prevent loss of time in handling at the factory.

When returning guns for service, please remove custom stocks and holsters. We cannot assume responsibility for these items.

When your revolver arrives in our Service Department, it will be very carefully inspected, together with your letter of instructions. Next, a quotation covering total cost of work to be performed will be sent to you. No actual work will be commenced before receiving your approval of our quotation unless you specifically authorize us to do so.

INSTRUCTIONS FOR USE

Care and Cleaning

Many weapons require stripping or at least partial disassembly in order to clean and oil them properly. This does not apply to the revolver, which may be cleaned and lubricated under all normal circumstances without removing a single pin or screw.

If at any time disassembly of the weapon is indicated for repairs, etc. it is recommended that the gun be returned to the factory, or you should at least employ the services of a qualified gunsmith.

To keep revolvers in proper condition, and to insure perfect functioning in time of need, it is essential that they be kept clean and coated with a rust inhibiting oil. Care is required to prevent rust, especially in damp, humid climates, or when sweaty hands come in contact with the guns.

To clean the revolver as required when the weapon is not fired, or when kept in storage, rub it externally with a lightly oiled cloth, and then swab out the bore and cylinder chambers with an oily flannel patch. Remove excess oil but leave a light film to protect the arm against rusting. Clean out all crevices with a small clean brush.

For cleaning after firing, scrub out the bore and chambers with an approved nitro solvent, and then use a brush dipped in solvent to remove all deposits from around the breech of the barrel, extractor head, and other adjacent areas which have been subjected to the action of powder or primer residue. If there is any evidence of lead particles, or other foreign matter left in bore or chambers, it is well to scrub these parts further with a bronze or brass brush dipped in powder solvent.

After cleaning off the entire gun with nitro or powder solvent, remove all traces of the solvent, both on the exterior of the gun and in the bore and chambers, following immediately thereafter with the application of a light film of oil. Note that there is usually some residue in the steel of both barrel and cylinder that works out and becomes apparent within from 24 hours to 48 hours after the initial cleaning. This can be removed with a bristle brush with perhaps a light re-application of powder solvent, after which the oil film should be re-established on all surfaces.

The above applies if ammunition used is of American manufacture, incorporating smokeless powders and non-corrosive primers. If other than smokeless powders and non-corrosive primers are used in these revolvers then cleaning methods should be adjusted accordingly.

Do not store revolvers with a plug in the barrel, since this is a contributing factor to sweating. By the same token, maintenance or storage rooms should be kept at a constant temperature with the least possible humidity, and the guns should *not* be stored encased in anything which will attract or hold moisture, such as leather.

If revolvers are to be stored for a long period of time, the internal mechanism of the lockwork should be heavily oiled with an acid free lubricating oil, and the exterior of the guns, as well as the bore of the barrel and the charge holes of the cylinder, should be heavily coated with an anti-rust oil. It is an established fact that moisture is the greatest enemy of metallic objects, particularly in climates where temperature and humidity are high,

and salt air is present. Extreme care should be exercised that all metallic surfaces be kept clean and oiled, and the wood stocks on the revolvers should be inspected for cracks caused by moisture. A periodical coat of raw linseed oil, well rubbed in with the hand, will help to prevent the splitting of stocks, but care must be exercised that the linseed oil does not get into the mechanism or on moving parts, as it has a tendency to gum when dry.

Function

Loading and firing this revolver is a comparatively simple operation, as follows:

Push the thumbpiece forward. This will release the cylinder so that it may be swung out to the left side for loading. Holding the gun so that the cylinder is in its outermost position, and with the muzzle pointing downward, insert cartridges in the charge holes making certain that they are firmly seated. Return the cylinder to its original position in the frame, pressing it firmly into place to make sure that it locks in alignment. The gun is now ready to fire.

To extract the fired cases press the thumbpiece forward and swing the cylinder out to the left side. Turn the gun muzzle upward and holding the cylinder in its extreme outward position press down sharply on the extractor rod. This will eject the fired cases down and out of the gun, which is now ready to reload.

Safety Precautions

Before proceeding to use this weapon, a word of caution is in order. This gun is as safe to handle and use as we can make it, but there is no foolproof firearm. Used correctly by a competent person the revolver is one of the safest handguns. There are many safety rules but those found below are basic, and should be observed rigidly until they become second nature.

1. The gun must always be checked for live ammunition when picked up, drawn from the holster, or handed to or accepted from another individual.
2. The gun should always be holstered except when drawn for a definite purpose.
3. Never point the revolver at anything that you do not intend to shoot.
4. Dry-snapping, even with dummy cartridges, should be discouraged unless same is performed on a regular target range or at a known inanimate target object.
5. When the handgun is out of the holster and held in a ready position, be absolutely certain that it is not pointing at any part of yourself or the persons of others who are in your immediate vicinity.
6. Beware of obstructions in the barrel. If, when firing, a weak or peculiar report is heard, cease firing at once and inspect the barrel for an obstruction. A stuck bullet, or any other object in the barrel, should be removed immediately, since even a plug of mud, snow, twigs, or an abnormal quantity of heavy grease in the bore, may result in a bulged or burst barrel.
7. At all times treat the revolver as the precision instrument that it actually is.

MAKE SAFE GUN HANDLING A HABIT. S&W U.S.A.

SMITH & WESSON, INC.

SPRINGFIELD, MASS., U.S.A.